

ER REGULATORY CONTACT RECORD

Date/Time March 19, 2004/1 30

Site Contact(s) Annette Primrose
Phone 303 966-4385

Regulatory Contact David Kruchek
Phone 303 692-3328

Agency CDPHE

Purpose of Contact 800-5 Sample Location CG33-000

Discussion

Location CG33-000 within IHSS Group 800-5 targets the sump for the B881 footing drain outfall. The sump is an approximately 3-foot diameter corrugated metal pipe. The depth of the sump will be measured prior to sampling to determine the correct interval. This location will be sampled on the southeast side of the sump. Two sample intervals will be collected. The first at the depth corresponding to the lowest part of the sump as measured and then at the next deeper sample interval.

Contact Record Prepared By Annette Primrose

Required Distribution

M Aguilar, USEPA
S Bell, DOE-RFFO
J Berardin, K-H
B Birk, DOE-RFFO
L Brooks, K-H ESS
M Broussard, K-H RISS
L Butler, K-H RISS
G Carnival, K-H RISS
N Castaneda, DOE-RFFO
C Deck, K-H Legal
S Gunderson, CDPHE
M Keating, K-H RISS
G Kleeman, USEPA
D Kruchek, CDPHE
D Mayo, K-H RISS

R McCallister, DOE-RFFO
J Mead, K-H ESS
S Nesta, K-H RISS
L Norland, K-H RISS
K North, K-H ESS
E Pottorff, CDPHE
A Primrose, K-H RISS
R Schassburger, DOE-RFFO
S Serreze, K-H RISS
D Shelton, K-H ESS
C Spreng, CDPHE
S Surovchak, DOE-RFFO
K Wiemelt, K-H RISS
C Zahm, K-H Legal

Additional Distribution

Gerry Kelly, KH Team

